

UTC

Start 2015-09 June Line P

- 0132 June 8/15 Started file 2015-09-0001
- Departing Pat Bay
- 0402 " " fixed GPS input (something must
have come loose?)
- 1449 June 9/15 Debubbler was empty, Sal signal
very spiky, . Flow was down to 0.2.
Opened up manifold valve.
- 1701 15 June The fluorescence has been constantly
increasing, it's up to almost 7 now!!!
UTC Take a filt/um-filt CHC + HPLC loop,
then start file 0002 to be able to look
at data.
- 2045 15-6/15 stopped logging to clean filter
- 2109 15/6/15 bypassed filter (switched hoses)
Restarted on file 0003
LOOP 75A-D chl samples taken
- 2153 16/6/15 Stopped logging to re-route plumbing

2329 16/6/15 Restart file 004
-bypassed filter completely

2209 17 June UTC

Start file 0005 heading east.
Finally called 2015-09

0239 19 June UTC

-0242 -accidental restart - file 006

1532 UTC 19 June

Metal pipe going from manifold to debubblers
broke.

Mike fixed it using the plastic end off the pond
filter outflow.

File 0007 started @ 1544.

0420 UTC 22 June: Shut down