

2019-005

TSG flow set 1227 local, 22 MAY

2019-006

LOCAL TIME 1900 2 JUNE
UTZ 0200 3 JUNE
TSG PLUGGED IN

0208 3 JUNE UTZ
SCS STARTED.

0218 UTZ WATER STARTED
FLOW VERY HIGH FOR ~ 5 MIN
11° DIFF BETWEEN INTAKE & LAB
GOT FLOW READY HIGH TO FLUSH →
0241: FLOW BACK TO 1.0, 12.8 VS 14.0

The TSG stopped working on 8 June. The monitor light stayed on green on the SCS display and no one noticed that the data were not updating.

2019

JUNE 17th Fixed TSG, problem was loose connector to the SCS computer due to bad solder joint.

2019

JUNE 18th system flushed with fresh water for 15 mins. Scott Rose