

MAR 05, 2022 2022-001 LINE P

1638 UTC LOOP SYSTEM SHOT DOWN

TSG ZERO FLOW NOT SURE WHAT THE PROBLEM WAS BUT SOMETHING TO DO WITH PUMP SYSTEM: POSSIBLE BLOCKAGE

HEAVY SEAS GUSTING TO 40 3-4M WAVES

SHUT VALVE TO TSG ON START UP BUT SOME RUST MAY HAVE GONE THROUGH

1650 RUNNING AGAIN - BALANCE TSG PUMPS TO 1

MAR 16 TSG STUCK ON 50.645 134.601 1.1 AT PUMPS
10 UTC STOP + RESTART

DESKTOP - 3 DOCS ① SCS - SETUP ..X
DOC X

GIVES OVERVIEW OF SCS SETUP

② GPS GATE SETTINGS - DATA SETUPS

3 COMPORTS ALL INFO

51.306 -127.88

16.03.22 KC10 → CPE1 SALT WATER SYTEM SHUT DOWN @ 1458
TO REPAIR HOSE BIB ON AFT DECK SALT WATER HOSE
START UP AGAIN @ 1525 51.243 -127.875