

2017-07-03 2337 UTC SZ

TSG & Seasave shipped, new RPI-P feed was entered due to lost settings following 2016 setup. Server has TSG feed coming in fine but SCS doesn't see correct data

SCC Config for TSG: Decimal 2016

Julian 60-18	26	8
Lat 21-33	4	4
Lat 38-47	4	4
Time 48-59	0	0
Scan 60-70	0	0
Conduct 75-86	4	4
Temp L.b 90-100	4	4
Temp Inlet 105-115	4	4
Sat 119-130	4	4
Floor 134-144	2	2
VO 147-154	2	2

~~stop output 159~~

↑

went back and set TST output to these decimal places and now SCS is happy.

2018-03-07 SZ

Server used for Line P SWL trip Feb 19 - March 6 "2018-01"

post-cruise comments:

- Microsoft Office not activated

Documents + set up info are ~~in~~ in folder USER\SCSAdmin\Documents

SCS data being written to ~~F:\SCS\DATA~~ F:\SWData\DATA

2018-05-08 SZ

Server used for Lapse 2018-39 SWL May 8-19

X Sounder, AVOS, Heading not coming in... assume they have not been hooked on.

TSG, NMEA GGA, VTC, RUC are coming in

- Heading on GPSgate ("Gyro") was closed and opened - now it is coming in. and being picked up by SCS (J"TECOM09

- Same for AVOS. GPSgate instructs "AVOS" closed & reopened. Now data are coming to SCS.

Note that ZDA

+ SDDPT
aren't working / aren't setup

But once 12 kHz sounder is on
the TCOM18-Knudsen 12 kHz
should start collecting data

2018-06-26 SZ

Setup for 2018-63 C30

CHS ~~has~~ asked us not to use
their monitor but would allow us to
use the monitor called "Knudsen Sounder"

They joined another VGA cable (black)
(securely w/ screws) to our grey
cable so it now runs directly
from the server to the monitor
(front of the)

Server started up fine.

GPS gate settings reviewed, updated
notes made in File on document
folder "SWL Server set-up 2018-06-26"

Reorganized instances so GPS from bridge
is back @ the top + green icon shines
when getting GPS data.

Reapplied Sounder from Bridge Filter for
"SDDPT". It's now coming in correctly

All freely coming in + going to SCS
correctly except Knudsen 12 kHz
'cause I haven't seen if it's on yet
+ have not fixed ~~it~~ started "K" software.

17 Jul 2018 0500 UTC - SZ

Lost TSG at some point even though SCS still shows green dot.

GPS gate:

"Error connecting to IP address".
Will wait till we are on station to try stopping restarting SCS / GPS gate / Seaside

17 Jul 2219 UTC - SZ

Turned 12kHz sounder off.

Bridge sounder working well (SSDPT) and reconnected to SCS. The 12kHz was noisy & overkill for ~50m depth.

Setup # display "NireCollection - C30 v2018-07-17" of SCS variables. sel