

2015-01

~~Feb~~ Feb 10
2015

A seapoint Fluorometer S/N 2356 has
been installed in-line for 2015-01 SR

(Also replumbed?)

Feb 12
2310

Restarted - stopped IP output some time
ago

2015-01-0002.hex

New file started 22:24 20-2-2015
2015-01-0003.hex

Feb 23/15

System shut Down 16:51 XB