


Latitude: 47° 36.063 N.

Longitude: 124° 32.107 W.

Corrected Depth: 34 m.

ECHOHAB HOAST



Date Deployed: 10 Aug 06
Anchor Deploy Time: 1123

Date	Time
<u>Oct. 14</u>	<u>0800</u>
	<u>0808</u>
	<u>0850</u>
	<u>0925</u>
	<u>1000</u>
	<u>1001</u>

Date Time PDT

Oct. 14 0800 - on station EH2-D for recovery

0808 - sent ARM + 0455 command x2 rec'd. positive response x2
RCD + Exec'd returned both times range was 164.

- seems to be riding high = released

- bridge monitoring its position.

- buoy not moving but conditions are flat calm - we hook on to tow it see if it is free - buoy still attached - released tension

0850 - sent Arm + release command again - positive responses but
buoy came free and towed after ship without tension.
- completed recovery without problem except loss of PAR sensor on the mast.

0925 - at FH04 for recovery.

- trouble getting consistent ranges

- ranges 166 - 157 as we approach. 144, 142

- lost contact with hull transducer - shallow water.

- moved back on to mooring location app. 1/2 cable off. used dunking transducer.
144, 143, ranges again.

- decided to move off and release. app. 1 cable off.

1000 - ranges 340-350

- sent 5A68 for release x2 rec'd + exec'd both times range 370-380 m.

1001 - sighted on surface. - recovery completed without incident.